

ATTACHMENT 2: Januburu

Photos of poor surface water management after first wet season rain event, December 20, 2009 (approx 11.50am)



Waterlogged lots cleared of vegetation prior to wet season

High velocity stormwater carrying sediment from cleared lot



Stormwater carrying sediment from cleared lot to drainage system



Detention basin – full after the first wet season rainfall event
Note: colour of water denoting high sediment load